



**JERSEY
COASTGUARD**



**PORT OF
JERSEY**

NOTICE TO MARINERS

Nº 3 of 2011

PETITE ANQUETTE STATUS

Mariners are advised that the top mark is missing from Petite Anquette beacon off Jerseys' south east coast, in position 49°08.45n 001°56.25w. The characteristics of this beacon will be changed during 2011. Until such time as it is changed, this navigational beacon will be without a topmark.

An updated Notice to Mariners will follow once work is complete.

A handwritten signature in black ink, appearing to read 'P. Moore'.

CAPTAIN PETER MOORE
Deputy Harbour Master

Chief Executive / Harbour Master: Cap



**PORT OF
JERSEY**



**JERSEY
COASTGUARD**

Index – 28 February 2011

2011			
Nº 3 of 2011	28/02/11	Petite Anquette Status	Temporary
Nº 2 of 2011	28/02/11	Annual Summary	Permanent
Nº 1 of 2011	28/02/11	Permanent Notices and Regulations	Permanent
2010			
Nº 6 of 2010	29/07/10	Remedial works in St. Aubin's Bay	Self Cancelling
Nº 5 of 2010	28/05/10	Reporting by Commercial Vessels	Permanent
Nº 4 of 2010	28/05/10	Operation of Jersey Coastguard	Permanent